G. R. S. 59] GPB—15 000—20 12 13

GENERAL AND REVENUE SECRETARIAT.

1906-07
~~191~~ .
(Dr. Wkrai)

File No. 468

Serial Nos.

Papers Filed.

*Month*_____

SUBJECT.

Repairs to a crack in one of the large Stone beams forming the roof of the Mahadwara of the Sri Ranganathaswami temple at Shrirangapatam—

PREVIOUS REFERENCES	LATER REFERENCES

Muz. 2]

No.

GOVERNMENT OF H. H. THE MAHARAJA OF MYSORE,
MUZRAI DEPARTMENT,
DATED BANGALORE, May 1907.

FROM

L. ANANTASAMI RAO, ESQ., B.A.,
SECRETARY TO THE GOVT. OF H. H. THE MAHARAJA OF MYSORE,
MUZRAI DEPARTMENT.

To

The Chief Engineer of Mysore,

Bangalore.

SIR,

During my last inspection of the Muzrai Institutions at Seringapatam, I noticed a crack in one of the large stone beams forming the roof of the Mahadwara of the Sri Ranganathaswami temple. I was informed that the crack had been in existence for many years past but it seems desirable that the crack should be carefully examined by an Officer of the P. W. Department. I am accordingly to request that you will be so good as to instruct a P. W. Officer to examine the place and, if it is necessary to undertake any works, to forward an estimate therefor to Government through the Deputy Commissioner, Mysore District.

I have the honor to be,

Sir,

Your most obedient servant,

Dft) 4/5/07

Secretary

No. 9256

Copy is forwarded to the Deputy Commissioner, Mysore with the request that the estimate, when received from the P.W. may be submitted to the Govt with information as to the savings credit of the Sri Ranganathaswami temple at Seringapatam.

By Order,

Dft)

Secretary.

GPM—1000—13-11-06